

# Q6002 Complete machine dismantling guide

*product:* Q6002

---

*data:* **2022-6-8**

---

*artificial:*

---

*audit:*

---

*approval:*


---

ID



CNCE (SZ) Co., LTD.

# Product explosion chart



## Tool list:

- 1、 cross screwdriver
- 2、 Torx screwdriver
- 3、 Tweezers
- 4、 Disassemble machine piece



Remove the battery cover




Loosen the two 16 screws of the pan with a screwdriver



Pry the bottom shell from the corner with your fingers



Remove two screws from the  
auxiliary plate





Remove the auxiliary plate main FPC buckle



Remove the motor and remove the USB board



## Remove the coaxial line



Open the buckle and  
remove the side key  
FPC



Remove the main  
FPC buckle



Remove the main FPC buckle and  
remove the four screws of the main  
board



Remove the main board



All disassembled parts

